

You are cordially invited to attend a full day refresher course on both Topcon 3D-Office and Pocket-3D

Don't miss this opportunity to brush up on all of the functionality of Pocket 3D as well as its interface with 3D Office.

The training will take place at our facility in Stow, MA and includes lunch.

Bunce Industries, LLC
873 Great Road / P.O. Box 720
Stow, MA 01775




Pocket-3D



&

3D-Office



Training



Proposed 3D Office Agenda

- ◇ Opening/Importing AutoCad files
- ◇ Understanding and processing control points
- ◇ Processing linework files
- ◇ Processing TIN surfaces
- ◇ Creating Alignments
- ◇ Exporting of all files to Pocket-3D
- ◇ File management techniques for project organization



Cost: Full Day Session \$450.00

Pocket 3D/3D Office Registration Form

Name: _____

Company Name: _____

Address: _____

City: _____

State: _____ Zipcode: _____

Phone No: _____

Please designate your session preference below:

_____ March 10th _____ March 24th

Additional days will be added as needed.

Any questions about the training can be directed to Steven Meier, Training and Support Manager, at (800) 421-0125.

Please Note: The registration form along with a check for the full amount of the class must be returned to Bunce Industries to guarantee your space in the class. Checks should be payable to Bunce Industries and mailed to 873 Great Rd., Stow, MA 01775. Don't delay in sending your registration forms in as class sizes will be limited to optimize personal attention to all attendees. A two week notification to cancel is required in order to receive a full refund.

Proposed Pocket 3D Agenda

- ◇ Review of all menu selections
- ◇ Review use of all data file types
- ◇ Staking and topo functions
- ◇ Onboard cogo functions
- ◇ Volume calculations in the field
- ◇ Complete hands-on training

Directions to the Stow office

From the North:

- * Take I-93, I-95 or Rt 3 south to I-495 south
- * Take Exit 27 off of I-495
- * Turn right at the end of the ramp onto Rt 117 East
- * Take Rt 117 2 mi. to Entering Stow sign on right.
- * Bunce is the first driveway on the left (at the ET & L office complex)
- * Training will take place in the 1 story building

From the South:

- * Take I-495 North to Exit 27
- * Turn left at the end of the ramp onto Rt 117 East
- * Follow balance of directions from the North above

From the West:

- * Take I-90 (Mass Pike) East to I-495 North
- * Follow balance of directions from South above