

You are cordially invited to attend a full day refresher course on Topcon's 3D-MC Software

Don't miss this opportunity to brush up on all of the techniques associated with 3D-MC as well as a review of GPS technology and how it applies to our industry.

The training will take place at our facility in Stow, MA and includes lunch.

Bunce Industries, LLC
873 Great Road / P.O. Box 720
Stow, MA 01775

TOPCON **3D-MC**



Training



Proposed 3D-MC Agenda

- ◇ Review process of 3D Machine Control using RTK-GPS
- ◇ Calibration of Control Box to machine
- ◇ Importing and selecting job files
- ◇ Views and options of control box display
- ◇ Features of the new version 9 software



Cost: Full Day Session \$395.00/person
Each additional person from the same company
\$350.00

3D-MC Registration Form

Name: _____

Company Name: _____

Address: _____

City: _____

State: _____ Zipcode: _____

Phone No: _____

Please designate your session preference below:

____2/24/11 ____3/9/11 ____3/24/11

Additional days will be added as needed.

Any questions about the training can be directed to Steven Meier, Training and Support Manager, at (800) 421-0125.

Please Note: The registration form along with a check for the full amount of the class must be returned to Bunce Industries to guarantee your space in the class. Checks should be payable to Bunce Industries and mailed to 873 Great Rd., Stow, MA 01775. Don't delay in sending your registration forms in as class sizes will be limited to optimize personal attention to all attendees. A two week notification to cancel is required in order to receive a full refund.



Directions to the Stow office

From the North:

- * Take I-93, I-95 or Rt 3 south to I-495 south
- * Take Exit 27 off of I-495
- * Turn right at the end of the ramp onto Rt 117 East
- * Take Rt 117 2 mi. to Entering Stow sign on right.
- * Bunce is the first driveway on the left (at the ET & L office complex)
- * Training will take place in the 1 story building

From the South:

- * Take I-495 North to Exit 27
- * Turn left at the end of the ramp onto Rt 117 East
- * Follow balance of directions from the North above

From the West:

- * Take I-90 (Mass Pike) East to I-495 North
- * Follow balance of directions from South above